NUCOR®
NUCOR-YAMATO STEEL COMPANY

Proposed Roll/Close Schedule
ISO 9001:2015 Registered

Updated October 11th, 2024

Close Dates for all items, if available, are shown immediately behind the status of the book week.
Status: C - Closed; E - Controlled; I - Inquire; O - Open; PS - Planned Stock; SA - Subject to Accumulation
All sections close at 4 PM CST on the date indicated. Inquire items can close at any time.

Week Beginning		13-Oct	20-Oct	27-Oct	3-Nov	10-Nov	17-Nov	24-Nov	1-Dec	
NYS Fiscal Week		42	43	44	45	46	47	48	49	Projected Next Week
Wide Flange	**Mill #**									
W44x16x230-408	2	Shutdown	41 C				>>>>	47 O		12/15-12/22 Wks
W40x16x199-655	2	Shutdown	41 C	41 C				48 O		12/15-12/22 Wks
W40x11.75x149-392	2	Shutdown		41 C				48 O		12/15-12/22 Wks
W36x17x487-652	2	Shutdown		43 C					49 O	12/29-1/5 Wks
W36x16 1/2x231-441	2	Shutdown		43 C					49 O	12/29-1/5 Wks
W36x12x135-387	2	Shutdown		43 C PS	43 C PS					12/1-12/8 Wks
W33x15 3/4x201-387	2	Shutdown			43 I 10/15					12/1-12/8 Wks
W33x11 1/2x118-169	2	Shutdown			43 I 10/15					12/1-12/8 Wks
W30x15x173-433	2	Shutdown			44 I 10/16					12/1-12/8 Wks
W30x10 1/2x90-148	2	Shutdown			44 O					12/1-12/8 Wks
W27x14x146-539	2	Shutdown			44 I 10/16					12/1-12/8 Wks
W27x10x84-129	2	Shutdown			>>>>	44 O				12/8-12/15 Wks
W24x12 3/4x104-370	2	Shutdown				45 O				12/8-12/15 Wks
W24x9x56-103	2	Shutdown				45 O				12/8-12/15 Wks
W24x7x55-62	1	Shutdown				45 O				12/8-12/15 Wks
W21x12 1/4x101-275	2	Shutdown				45 O				1/5-1/12 Wks
W21x8 1/4x48-93	1	Shutdown				>>>>	46 O			12/8-12/15 Wks
W21x6 1/2x44-57	1	Shutdown				>>>>	46 O			12/8-12/15 Wks
W18x11x76-311	2	Shutdown	41 C PS				47 O			12/8-12/15 Wks
W18x7 1/2x41-71	1	Shutdown	41 C PS				>>>>	47 O		12/15-12/22 Wks
W18x6x35-46	1	Shutdown	41 C PS				>>>>	47 O		12/15-12/22 Wks
W16x10 1/4x67-100	1	Shutdown	42 C PS					48 O		12/15-12/22 Wks
W16x7x36-57	1	Shutdown	42 C PS					48 O		12/15-12/22 Wks
W16x5 1/2x26-31	1	Shutdown			44 I 10/17					12/8-12/15 Wks
W14x16x455-873	2	Shutdown	40 C			>>>>	46 O			12/8-12/15 Wks
W14x16x145-426	2	Shutdown	40 C			46 O	46 O			12/8-12/15 Wks
W14x14 1/2x90-132	2	Shutdown	40 C PS				46 O			12/8-12/15 Wks
W14x10x61-82	1	Shutdown	40 C PS				47 O			12/8-12/15 Wks
W14x8x43-53	1	Shutdown	40 C PS				>>>>	47 O		12/8-12/15 Wks
W14x6 3/4x30-38	1	Shutdown	43 C PS						49 O	12/22-12/29 Wks
W14x5x22-26	1	Shutdown			44 I 10/17					12/8-12/15 Wks
W12x12x65-336	2	Shutdown	41 C PS				47 O	47 O		12/15-12/22 Wks
W12x10x53-58	1	Shutdown	43 C PS						49 O	12/22-12/29 Wks
W12x8x40-50	1	Shutdown	43 C PS						49 O	12/22-12/29 Wks
W12x6 1/2x26-35	1	Shutdown		44 I 10/14						12/1-12/8 Wks
W12x4x16-22	1	Shutdown			>>>>	45 O				1/5-1/12 Wks
W10x10x49-112	1	Shutdown	43 C PS							12/1-12/8 Wks
W10x8x33-45	1	Shutdown		43 C PS						12/1-12/8 Wks
W10x5 3/4x22-30	1	Shutdown		44 I 10/14						12/1-12/8 Wks
W8x8x31-67	1	Shutdown		44 I 10/15						12/1-12/8 Wks
W8x6 1/2x24-28	1	Shutdown		44 I 10/15						12/1-12/8 Wks
W8x5 1/4x18-21	1	Shutdown		43 C PS						12/29-1/5 Wks
W6x6x15-25	1	Shutdown		43 C PS						12/29-1/5 Wks
Stand Sections		13-Oct	20-Oct	27-Oct	3-Nov	10-Nov	17-Nov	24-Nov	1-Dec	
MC18x4x42.7-58	1	Shutdown			44 O					12/29-1/5 Wks
MC13x4x31.8x50	1	Shutdown		44 I 10/15						12/29-1/5 Wks
MC12x4x31-50	1	Shutdown		44 I 10/15						12/29-1/5 Wks
C15x3 3/8x33.9-50	1	Shutdown		43 I 10/14						12/29-1/5 Wks
C12x3x20.7-30	1	Shutdown		43 I 10/14						12/29-1/5 Wks
L8x8x1/2" - 1 1/8"	1	Shutdown								12/8-12/15 Wks
L8x6x1/2" - 1"	1	Shutdown								12/8-12/15 Wks
L8x4x1/2"-1"	1	Shutdown								12/8-12/15 Wks
CZ13x41.2-51.2	1	Shutdown								TBA
S24x80-121	1	Shutdown				>>>>	45 O			1/5-1/12 Wks
S20x66-96	1	Shutdown				>>>>	46 O			1/5-1/12 Wks
S18x54.7-70	1	Shutdown								12/15-12/22 Wks
S15x42.9-50	1	Shutdown								12/8-12/15 Wks
S12x31.8-50	1	Shutdown								12/1-12/8 Wks
Piling Sections		13-Oct	20-Oct	27-Oct	3-Nov	10-Nov	17-Nov	24-Nov	1-Dec	
PS31	1	Shutdown			45 O					1/5-1/12 Wks
PS27	1	Shutdown			45 O					1/5-1/12 Wks
PZ40	1	Shutdown					48 O	<<<<		1/12-1/19 Wks
PZ35	1	Shutdown					48 O	<<<<		1/12-1/19 Wks
PZ27	1	Shutdown				47 O	<<<<			1/5-1/12 Wks
PZ22	1	Shutdown				47 O	<<<<			1/5-1/12 Wks
HP18	2	Shutdown								12/1-12/8 Wks
HP16	2	Shutdown	40 C							12/8-12/15 Wks
HP14x14.5x73-117	2	Shutdown	40 C				46 O			12/8-12/15 Wks
HP12x12x53-84	2	Shutdown	41 C				>>>>	47 O		12/15-12/22 Wks
HP10x10x42-57	1	Shutdown								12/1-12/8 Wks
HP8x8x36	1	Shutdown		44 I 10/15						12/1-12/8 Wks

W44 x 368 | W44 x 408 | W40 x 655 | W27 x 539 | W14 x 808 | W36 x 286 | W36 x 318 | W36 x 350 | W36 x 387

NEW
WIDE FLANGE JUMBO SECTIONS