

Close Dates for all items, if available, are shown immediately behind the status of the book week.
Status: C - Closed; E - Controlled; I - Inquire; O - Open; PS - Planned Stock; SA - Subject to Accumulation
All sections close at 4 PM CST on the date indicated. Inquire items can close at any time.

| Week Beginning | | 6-Oct | 13-Oct | 20-Oct | 27-Oct | 3-Nov | 10-Nov | 17-Nov | 24-Nov | Projected Next Week |
|--------------------|--------|---------|----------|-----------|------------|------------|--------|--------|--------|---------------------|
| NYS Fiscal Week | | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | |
| Wide Flange | Mill # | | | | | | | | | |
| W44x16x230-408 | 2 | | Shutdown | 41 10/8 | | | | 47 O | | 12/15-12/22 Wks |
| W40x16x199-655 | 2 | | Shutdown | 41 10/8 | 41 10/8 | | | | 48 O | 12/15-12/22 Wks |
| W40x11.75x149-392 | 2 | | Shutdown | >>>> | 41 10/8 | | | | 48 O | 12/15-12/22 Wks |
| W36x17x487-652 | 2 | | Shutdown | | 43 10/9 | | | | | 11/24-12/1 Wks |
| W36x16 1/2x231-441 | 2 | | Shutdown | | 43 10/9 | | | | | 11/24-12/1 Wks |
| W36x12x135-387 | 2 | | Shutdown | | 43 10/9 | | | | | 11/24-12/1 Wks |
| W33x15 3/4x201-387 | 2 | | Shutdown | | 43 10/15 | 43 10/15 | | | | 11/24-12/1 Wks |
| W33x11 1/2x118-169 | 2 | | Shutdown | | >>>> | 43 10/15 | | | | 11/24-12/1 Wks |
| W30x15x173-433 | 2 | | Shutdown | | >>>> | 44 10/16 | | | | 11/24-12/1 Wks |
| W30x10 1/2x90-148 | 2 | | Shutdown | | | 44 O | | | | 11/24-12/1 Wks |
| W27x14x146-539 | 2 | | Shutdown | | | 44 10/16 | | | | 12/1-12/8 Wks |
| W27x10x84-129 | 2 | | Shutdown | | | 44 O | | | | 12/1-12/8 Wks |
| W24x12 3/4x104-370 | 2 | | Shutdown | | | 45 O | 45 O | | | 12/1-12/8 Wks |
| W24x9x56-103 | 2 | 39 C PS | Shutdown | | | >>>> | 45 O | | | 12/1-12/8 Wks |
| W24x7x55-62 | 1 | | Shutdown | | | | 45 O | | | 12/8-12/15 Wks |
| W21x12 1/4x101-275 | 2 | | Shutdown | | | >>>> | 45 O | | | 12/29-1/5 Wks |
| W21x8 1/4x48-93 | 1 | 40 C PS | Shutdown | | | | 46 O | | | 12/8-12/15 Wks |
| W21x6 1/2x44-57 | 1 | 40 C PS | Shutdown | | | | 46 O | | | 12/8-12/15 Wks |
| W18x11x76-311 | 2 | | Shutdown | 41 C PS | | | | 47 O | | 12/8-12/15 Wks |
| W18x7 1/2x41-71 | 1 | | Shutdown | 41 C PS | | | | 47 O | | 12/15-12/22 Wks |
| W18x6x35-46 | 1 | | Shutdown | 41 C PS | | | | 47 O | | 12/15-12/22 Wks |
| W16x10 1/4x67-100 | 1 | | Shutdown | 42 C PS | | | | | 48 O | 12/15-12/22 Wks |
| W16x7x36-57 | 1 | | Shutdown | 42 C PS | | | | | 48 O | 12/15-12/22 Wks |
| W16x5 1/2x26-31 | 1 | | Shutdown | | | 44 10/17 | | | | 12/1-12/8 Wks |
| W14x16x455-873 | 2 | | Shutdown | 40 C | | | 46 O | | | 12/8-12/15 Wks |
| W14x16x145-426 | 2 | 40 C | Shutdown | | | | 46 O | | | 12/8-12/15 Wks |
| W14x14 1/2x90-132 | 2 | | Shutdown | 40 C PS | | | 46 O | 46 O | | 12/8-12/15 Wks |
| W14x10x61-82 | 1 | 40 C PS | Shutdown | 40 C PS | | | | 47 O | | 12/8-12/15 Wks |
| W14x8x43-53 | 1 | | Shutdown | 40 C PS | | | | 47 O | | 12/8-12/15 Wks |
| W14x6 3/4x30-38 | 1 | | Shutdown | 43 C PS | | | | | | 11/24-12/1 Wks |
| W14x5x22-26 | 1 | | Shutdown | | | 44 10/17 | | | | 12/1-12/8 Wks |
| W12x12x65-336 | 2 | | Shutdown | 41 C PS | | | | 47 O | | 12/8-12/15 Wks |
| W12x10x53-58 | 1 | | Shutdown | 43 C PS | | | | | | 11/24-12/1 Wks |
| W12x8x40-50 | 1 | | Shutdown | 43 C PS | | | | | | 11/24-12/1 Wks |
| W12x6 1/2x26-35 | 1 | | Shutdown | | 44 10/14 | | | | | 11/24-12/1 Wks |
| W12x4x16-22 | 1 | | Shutdown | | | 45 O | | | | 12/22-12/29 Wks |
| W10x10x49-112 | 1 | | Shutdown | 43 C PS | | | | | | 11/24-12/1 Wks |
| W10x8x33-45 | 1 | | Shutdown | 43 C PS | 43 C PS | | | | | 11/24-12/1 Wks |
| W10x5 3/4x22-30 | 1 | | Shutdown | | 44 10/14 | | | | | 11/24-12/1 Wks |
| W8x8x31-67 | 1 | | Shutdown | | 44 10/15 | | | | | 11/24-12/1 Wks |
| W8x6 1/2x24-28 | 1 | | Shutdown | | 44 10/15 | | | | | 11/24-12/1 Wks |
| W8x5 1/4x18-21 | 1 | | Shutdown | | 43 C PS | | | | | 12/25-12/22 Wks |
| W6x6x15-25 | 1 | | Shutdown | | 43 C PS | | | | | 12/25-12/22 Wks |
| Stand Sections | | 6-Oct | 13-Oct | 20-Oct | 27-Oct | 3-Nov | 10-Nov | 17-Nov | 24-Nov | |
| MC18x4x42.7-58 | 1 | | Shutdown | | | 44 O | | | | 12/25-12/22 Wks |
| MC13x4x31.8x50 | 1 | | Shutdown | | 44 10/15 | 44 10/15 | | | | 12/25-12/22 Wks |
| MC12x4x31-50 | 1 | | Shutdown | | 44 10/15 | | | | | 12/25-12/22 Wks |
| C15x3 3/8x33.9-50 | 1 | | Shutdown | | 43 10/14 | | | | | 12/25-12/22 Wks |
| C12x3x20.7-30 | 1 | | Shutdown | | 43 10/14 | | | | | 12/25-12/22 Wks |
| L8x8x1/2" - 1 1/8" | 1 | | Shutdown | | | | | | | 12/1-12/8 Wks |
| L8x6x1/2" - 1" | 1 | | Shutdown | | | | | | | 12/1-12/8 Wks |
| L8x4x1/2"-1" | 1 | | Shutdown | | | | | | | 12/1-12/8 Wks |
| CZ13x41.2-51.2 | 1 | | Shutdown | | | | | | | TBA |
| S24x80-121 | 1 | | Shutdown | | | | 45 O | | | 1/5-1/12 Wks |
| S20x66-96 | 1 | | Shutdown | | | | 46 O | | | 1/5-1/12 Wks |
| S18x54.7-70 | 1 | | Shutdown | | | | | | | 12/15-12/22 Wks |
| S15x42.9-50 | 1 | | Shutdown | | | | | | | 11/17-11/24 Wks |
| S12x31.8-50 | 1 | | Shutdown | | | | | | | 11/24-12/1 Wks |
| Piling Sections | | 6-Oct | 13-Oct | 20-Oct | 27-Oct | 3-Nov | 10-Nov | 17-Nov | 24-Nov | |
| PS31 | 1 | | Shutdown | | | 45 O | | | | 12/22-12/29 Wks |
| PS27 | 1 | | Shutdown | | | 45 O | | | | 12/22-12/29 Wks |
| PZ40 | 1 | | Shutdown | | | | | | 48 O | 1/5-1/12 Wks |
| PZ35 | 1 | | Shutdown | | | | | | 48 O | 1/5-1/12 Wks |
| PZ27 | 1 | | Shutdown | | | | | 47 O | | 1/5-1/12 Wks |
| PZ22 | 1 | | Shutdown | | | | | 47 O | | 1/5-1/12 Wks |
| HP18 | 2 | 39 C | Shutdown | | | | | | | 12/1-12/8 Wks |
| HP16 | 2 | >>>> | Shutdown | 40 C | | | | | | 12/8-12/15 Wks |
| HP14x14.5x73-117 | 2 | | Shutdown | 40 C | | | >>>> | 46 O | | 12/8-12/15 Wks |
| HP12x12x53-84 | 2 | | Shutdown | 41 C | | | | 47 O | | 12/8-12/15 Wks |
| HP10x10x42-57 | 1 | | Shutdown | | | | | | | 11/24-12/1 Wks |
| HP8x8x36 | 1 | | Shutdown | | 44 10/15 | | | | | 11/24-12/1 Wks |

