

Close Dates for all items, if available, are shown immediately behind the status of the book week.
 Status: C - Closed; E - Controlled; I - Inquire; O - Open; PS - Planned Stock; SA - Subject to Accumulation
 All sections close at 4 PM CST on the date indicated. Inquire items can close at any time.

Week Beginning		3-Mar	10-Mar	17-Mar	24-Mar	31-Mar	7-Apr	14-Apr	21-Apr	Projected Next Week
NYS Fiscal Week	Mill #	10	11	12	13	14	15	16	17	
Wide Flange										
W44x16x230-408	2		11 C	11 C			shutdown		17 O	5/26-6/2 Wks
W40x16x199-655	2			11 C			shutdown		17 O	5/26-6/2 Wks
W40x11.75x149-392	2			11 C			shutdown		17 O	5/26-6/2 Wks
W36x17x487-652	2			11 C			shutdown			4/21-4/28 Wks
W36x16 1/2x231-441	2			11 C			shutdown			4/21-4/28 Wks
W36x12x135-387	2			11 C PS			shutdown			4/21-4/28 Wks
W33x15 3/4x201-387	2			11 C			shutdown			4/28-5/5 Wks
W33x11 1/2x118-169	2			11 C PS	11 C PS		shutdown			4/28-5/5 Wks
W30x15x173-433	2				12 C		shutdown			4/28-5/5 Wks
W30x10 1/2x90-148	2				12 I 3/12		shutdown			4/28-5/5 Wks
W27x14x146-539	2				12 C		shutdown			4/28-5/5 Wks
W27x10x84-129	2				12 I 3/12		shutdown			4/28-5/5 Wks
W24x12 3/4x104-370	2				13 I 3/13		shutdown			5/5-5/12 Wks
W24x9x56-103	2				13 I 3/13	13 I 3/13	shutdown			5/5-5/12 Wks
W24x7x55-62	1			12 C PS					shutdown	5/12-5/19 Wks
W21x12 1/4x101-275	2					13 I 3/13	shutdown			5/5-5/12 Wks
W21x8 1/4x48-93	1			13 C					shutdown	5/12-5/19 Wks
W21x6 1/2x44-57	1			13 C PS					shutdown	5/12-5/19 Wks
W18x11x76-311	2		10 C PS				shutdown	16 O		5/19-5/26 Wks
W18x7 1/2x41-71	1				14 I 3/11				shutdown	5/19-5/26 Wks
W18x6x35-46	1				14 I 3/11	14 I 3/11			shutdown	5/19-5/26 Wks
W16x10 1/4x67-100	1					14 I 3/12			shutdown	5/19-5/26 Wks
W16x7x36-57	1					14 I 3/12			shutdown	5/19-5/26 Wks
W16x5 1/2x26-31	1		12 C PS						shutdown	4/21-4/28 Wks
W14x16x455-808	2	09 C					shutdown	14 O		5/12-5/19 Wks
W14x16x145-426	2	09 C				14 O	shutdown	14 O		5/12-5/19 Wks
W14x14 1/2x90-132	2	10 C PS					shutdown	16 O		5/19-5/26 Wks
W14x10x61-82	1			13 C	<<<<				shutdown	5/19-5/26 Wks
W14x8x43-53	1			13 I 3/11	<<<<				shutdown	5/19-5/26 Wks
W14x6 3/4x30-38	1	11 C PS				14 I 3/12			shutdown	5/26-6/2 Wks
W14x5x22-26	1		12 C PS						shutdown	4/21-4/28 Wks
W12x12x65-336	2		10 C PS				shutdown		17 O	5/26-6/2 Wks
W12x10x53-58	1	11 C PS				15 I 3/12	<<<<		shutdown	5/26-6/2 Wks
W12x8x40-50	1	11 C PS				15 I 3/12	<<<<		shutdown	5/26-6/2 Wks
W12x6 1/2x26-35	1	12 C PS						16 O	shutdown	6/2-6/9 Wks
W12x4x16-22	1								shutdown	5/5-5/12 Wks
W10x10x49-112	1	11 C PS					15 I 3/13		shutdown	5/26-6/2 Wks
W10x8x33-45	1	11 C PS					15 I 3/13		shutdown	5/26-6/2 Wks
W10x5 3/4x22-30	1	>>>>	11 C PS					16 O	shutdown	6/2-6/9 Wks
W8x8x31-67	1	>>>>	11 C PS					16 O	shutdown	6/2-6/9 Wks
W8x6 1/2x24-28	1		11 C PS					16 O	shutdown	6/2-6/9 Wks
W8x5 1/4x18-21	1	12 C PS					15 O		shutdown	5/26-6/2 Wks
W6x6x15-25	1	12 C PS					15 O		shutdown	5/26-6/2 Wks
Stand Sections										
MC18x4x42.7-58	1								shutdown	4/21-4/28 Wks
MC13x4x31.8x50	1								shutdown	TBA
MC12x4x31-50	1							16 O	shutdown	7/7-7/14 Wks
C15x3 3/8x33.9-50	1							16 O	shutdown	7/7-7/14 Wks
C12x3x20.7-30	1							16 O	shutdown	7/7-7/14 Wks
L8x8x1/2" - 1 1/8"	1		11 C PS						shutdown	6/2-6/9 Wks
L8x6x1/2" - 1"	1		11 C PS						shutdown	6/2-6/9 Wks
L8x4x1/2"-1"	1		11 C PS						shutdown	6/2-6/9 Wks
CZ13x41.2-51.2	1								shutdown	TBA
S24x80-121	1								shutdown	TBA
S20x66-96	1								shutdown	TBA
S18x54.7-70	1					14 I 3/11			shutdown	TBA
S15x42.9-50	1								shutdown	5/26-6/2 Wks
S12x31.8-50	1	12 C PS							shutdown	5/19-5/26 Wks
Piling Sections										
PS31	1								shutdown	5/5-5/12 Wks
PS27	1								shutdown	5/5-5/12 Wks
PZ40	1								shutdown	5/12-5/19 Wks
PZ35	1								shutdown	5/12-5/19 Wks
PZ27	1								shutdown	5/19-5/26 Wks
PZ22	1								shutdown	5/19-5/26 Wks
HP18	2					13 O	shutdown			TBA
HP16	2	09 C					shutdown			5/12-5/19 Wks
HP14x14.5x73-117	2		10 C				shutdown	16 O		5/19-5/26 Wks
HP12x12x53-84	2		10 C				shutdown		17 O	5/26-6/2 Wks
HP10x10x42-57	1	11 C					15 I 3/13		shutdown	5/26-6/2 Wks
HP8x8x36	1							16 O	shutdown	6/2-6/9 Wks

