

Close Dates for all items, if available, are shown immediately behind the status of the book week.  
 Status: C - Closed; E - Controlled; I - Inquire; O - Open; PS - Planned Stock; SA - Subject to Accumulation

All sections close at 4 PM CST on the date indicated. Inquire items can close at any time.

| Week Beginning         |        | 12-May        | 19-May        | 26-May        | 2-Jun        | 9-Jun        | 16-Jun        | 23-Jun        | 30-Jun        | Projected Next Week |
|------------------------|--------|---------------|---------------|---------------|--------------|--------------|---------------|---------------|---------------|---------------------|
| NYS Fiscal Week        | Mill # | 20            | 21            | 22            | 23           | 24           | 25            | 26            | 27            |                     |
| Wide Flange            | Mill # |               |               |               |              |              |               |               |               |                     |
| W44x16x230-408         | 2      |               |               | 21 I 5/16     |              |              |               | 26 O          |               | 7/21-7/28 Wks       |
| W40x16x199-655         | 2      |               |               | 22 I 5/16     | 22 I 5/16    |              |               |               | 27 O          | 7/28-8/4 Wks        |
| W40x11.75x149-392      | 2      |               |               |               | 22 I 5/16    |              |               |               | 27 O          | 7/28-8/4 Wks        |
| W36x17x487-652         | 2      |               |               |               | 22 I 5/17    |              |               |               | 27 O          | 7/28-8/4 Wks        |
| W36x16 1/2x231-441     | 2      |               |               |               | 22 I 5/17    |              |               |               | 27 O          | 7/28-8/4 Wks        |
| W36x12x135-387         | 2      | 17 C PS       |               |               | 22 I 5/17    |              |               |               | 27 O          | 7/28-8/4 Wks        |
| W33x15 3/4x201-387     | 2      | 18 C          |               |               | 23 I 5/17    |              |               |               |               | 6/30-7/7 Wks        |
| W33x11 1/2x118-169     | 2      | 18 C PS       |               |               | 23 I 5/17    |              |               |               |               | 6/30-7/7 Wks        |
| W30x15x173-433         | 2      | 18 C          |               |               | 23 I 5/20    |              |               |               |               | 6/30-7/7 Wks        |
| W30x10 1/2x90-148      | 2      | 18 C PS       |               |               |              | 23 O         |               |               |               | 6/30-7/7 Wks        |
| W27x14x146-539         | 2      | 19 C          |               |               |              | 24 I 5/20    |               |               |               | 7/7-7/14 Wks        |
| W27x10x84-129          | 2      | 19 C PS       | 19 C PS       |               |              | 24 O         |               |               |               | 7/7-7/14 Wks        |
| W24x12 3/4x104-370     | 2      |               | 19 C PS       |               |              | 24 O         |               |               |               | 7/7-7/14 Wks        |
| W24x9x56-103           | 2      |               | 19 C PS       |               |              | 24 O         |               |               |               | 7/7-7/14 Wks        |
| W24x7x55-62            | 1      |               |               | 21 C PS       |              |              |               | 26 O          |               | 7/21-7/28 Wks       |
| W21x12 1/4x101-275     | 2      |               |               |               |              | 24 O         |               |               |               | 7/7-7/14 Wks        |
| W21x8 1/4x48-93        | 1      |               |               | 22 C PS       |              |              |               |               | 27 O          | 7/28-8/4 Wks        |
| W21x6 1/2x44-57        | 1      |               |               | 22 C PS       |              |              |               |               | 27 O          | 7/28-8/4 Wks        |
| W18x11x76-311          | 2      |               |               | 21 C PS       |              |              |               | 26 O          |               | 7/21-7/28 Wks       |
| W18x7 1/2x41-71        | 1      | 20 C PS       |               | >>>>          | 22 I 5/15    |              |               |               |               | 6/30-7/7 Wks        |
| W18x6x35-46            | 1      | 20 C PS       |               |               | 22 I 5/15    |              |               |               |               | 6/30-7/7 Wks        |
| W16x10 1/4x67-100      | 1      | 20 C          |               |               | >>>>         | 23 I 5/15    |               |               |               | 6/30-7/7 Wks        |
| W16x7x36-57            | 1      | 20 C PS       |               |               | >>>>         | 23 I 5/15    |               |               |               | 6/30-7/7 Wks        |
| W16x5 1/2x26-31        | 1      |               | 21 C PS       | 21 C PS       |              |              | 25 O          |               |               | 7/14-7/21 Wks       |
| W14x16x455-808         | 2      |               | >>>>          | 20 C          |              |              | 25 O          |               |               | 7/14-7/21 Wks       |
| W14x16x145-426         | 2      |               | 20 C          |               |              | 25 O         | 25 O          |               |               | 7/14-7/21 Wks       |
| W14x14 1/2x90-132      | 2      |               |               | 21 C PS       |              |              |               | 26 O          |               | 7/14-7/21 Wks       |
| W14x10x61-82           | 1      |               |               | 22 C PS       |              |              |               |               | 27 O          | 7/28-8/4 Wks        |
| W14x8x43-53            | 1      |               |               | 22 I 5/15     | 22 I 5/15    |              |               |               | 27 O          | 7/28-8/4 Wks        |
| W14x6 3/4x30-38        | 1      | 20 C PS       |               |               | >>>>         | 23 I 5/16    |               |               |               | 6/30-7/7 Wks        |
| W14x5x22-26            | 1      |               | >>>>          | 21 C PS       |              |              | 25 O          |               |               | 7/14-7/21 Wks       |
| W12x12x65-336          | 2      |               |               | 21 C PS       |              |              |               | 26 O          |               | 7/21-7/28 Wks       |
| W12x10x53-58           | 1      | 20 C PS       |               |               |              | 23 I 5/16    |               |               |               | 6/30-7/7 Wks        |
| W12x8x40-50            | 1      | 20 C PS       |               |               |              | 23 I 5/16    |               |               |               | 6/30-7/7 Wks        |
| W12x6 1/2x26-35        | 1      | >>>>          | 20 C PS       |               |              |              | 25 O          |               |               | 7/14-7/21 Wks       |
| W12x4x16-22            | 1      |               |               |               |              |              | 25 O          |               |               | 7/14-7/21 Wks       |
| W10x10x49-112          | 1      | 20 C PS       |               |               |              | 24 I 5/17    |               |               |               | 7/7-7/14 Wks        |
| W10x8x33-45            | 1      | 20 C PS       |               |               |              | 24 I 5/17    |               |               |               | 7/7-7/14 Wks        |
| W10x5 3/4x22-30        | 1      |               | 21 C PS       |               |              |              | 25 O          |               |               | 7/14-7/21 Wks       |
| W8x8x31-67             | 1      |               | 21 C PS       |               |              |              | 25 O          |               |               | 7/14-7/21 Wks       |
| W8x6 1/2x24-28         | 1      |               | 21 C PS       |               |              |              | 25 O          |               |               | 7/14-7/21 Wks       |
| W8x5 1/4x18-21         | 1      | >>>>          | 20 C PS       |               |              | 24 O         |               |               |               | 7/7-7/14 Wks        |
| W6x6x15-25             | 1      | >>>>          | 20 C PS       |               |              | 24 O         |               |               |               | 7/7-7/14 Wks        |
| <b>Stand Sections</b>  |        | <b>12-May</b> | <b>19-May</b> | <b>26-May</b> | <b>2-Jun</b> | <b>9-Jun</b> | <b>16-Jun</b> | <b>23-Jun</b> | <b>30-Jun</b> |                     |
| MC18x4x42.7-58         | 1      |               |               |               |              |              | 25 O          |               |               | 8/11-8/18 Wks       |
| MC13x4x31.8x50         | 1      |               |               |               |              |              |               |               |               | TBA                 |
| MC12x4x31-50           | 1      |               |               |               |              |              | 25 O          |               |               | 8/11-8/18 Wks       |
| C15x3 3/8x33.9-50      | 1      |               |               |               |              | >>>>         | 24 O          |               |               | 8/4-8/11 Wks        |
| C12x3x20.7-30          | 1      |               |               |               |              | 24 O         | 24 O          |               |               | 8/4-8/11 Wks        |
| L8x8x1/2" - 1 1/8"     | 1      |               | 21 C PS       |               |              |              |               |               |               | 7/14-7/21 Wks       |
| L8x6x1/2" - 1"         | 1      |               |               |               |              |              |               |               |               | 7/14-7/21 Wks       |
| L8x4x1/2"-1"           | 1      |               |               |               |              |              |               |               |               | 7/14-7/21 Wks       |
| CZ13x41.2-51.2         | 1      |               | >>>>          | 22 C          |              |              |               |               |               | TBA                 |
| S24x80-121             | 1      |               |               |               |              |              |               | 26 O          |               | TBA                 |
| S20x66-96              | 1      |               |               |               |              |              |               |               | 27 O          | TBA                 |
| S18x54.7-70            | 1      |               |               |               |              | 23 I 5/16    |               |               |               | TBA                 |
| S15x42.9-50            | 1      |               | >>>>          | 21 C PS       |              |              |               |               |               | TBA                 |
| S12x31.8-50            | 1      |               | 20 C PS       |               |              |              |               |               |               | 7/14-7/21 Wks       |
| <b>Piling Sections</b> |        | <b>12-May</b> |               |               |              |              |               |               |               |                     |
| PS31                   | 1      |               |               |               |              |              |               |               |               | 7/7-7/14 Wks        |
| PS27                   | 1      |               |               |               |              |              |               |               |               | 7/7-7/14 Wks        |
| PZ40                   | 1      |               |               |               |              |              |               |               |               | 6/30-7/7 Wks        |
| PZ35                   | 1      |               |               |               |              |              |               |               |               | 6/30-7/7 Wks        |
| PZ27                   | 1      |               |               |               |              |              |               | 26 O          |               | 8/11-8/18 Wks       |
| PZ22                   | 1      |               |               |               |              |              |               | 26 O          |               | 8/11-8/18 Wks       |
| HP18                   | 2      |               | 20 C          |               |              |              |               |               |               | TBA                 |
| HP16                   | 2      |               | 20 C          |               |              |              |               |               |               | TBA                 |
| HP14x14.5x73-117       | 2      |               | 21 C          | 21 C          |              |              |               | 26 O          |               | 7/14-7/21 Wks       |
| HP12x12x53-84          | 2      |               |               | 21 C          |              |              |               | 26 O          |               | 7/21-7/28 Wks       |
| HP10x10x42-57          | 1      | 20 C          |               |               |              | 24 I 5/17    |               |               |               | 7/7-7/14 Wks        |
| HP8x8x36               | 1      |               | 21 C          |               |              |              | 25 O          |               |               | 7/14-7/21 Wks       |

