

Nucor-Yamato Proposed Roll/Close Schedule * ISO 9001:2008 Registered * August 16, 2017

American Made / ASTM Compliant

Inquire items are followed immediately by the close date of the book week --- Highlighted items will close in the next week

Week Beginning		13-Aug	20-Aug	27-Aug	3-Sep	10-Sep	17-Sep	24-Sep	1-Oct	
NYS Fiscal Month		Aug	Aug	Sep	Sep	Sep	Sep	Sep	Oct	
NYS Fiscal Week		33	34	35	36	37	38	39	40	
Wide Flange Sections	Mill #									Projected next roll week
W44x16x230-335	2			36 8/17		Shutdown				11/5-11/12 Wks
W40x16x199-503	2			36 8/17	36 8/17	Shutdown				11/5-11/12 Wks
W40x12x149-327	2			>>>>	36 8/17	Shutdown				10/8-10/15 Wks
W36x17x487-529	2			>>>>	36 8/17	Shutdown				10/8-10/15 Wks
W36x16.5x231-441	2			>>>>	36 8/17	Shutdown				10/8-10/15 Wks
W36x12x135-256	2				36 8/24	Shutdown				10/8-10/15 Wks
W33x15.75x201-387	2				38 8/21	Shutdown				10/8-10/15 Wks
W33x11.5x118-169	2				38 8/24	Shutdown				10/8-10/15 Wks
W30x15x173-391	2				38 8/21	Shutdown	38 8/21			10/8-10/15 Wks
W30x10.5x90-148	2					Shutdown	38 8/30			10/15-10/22 Wks
W27x14x146-368	2	32 C				Shutdown	38 8/30			10/15-10/22 Wks
W27x10x84-129	2	32 C PS				Shutdown	38 8/30			10/15-10/22 Wks
W24x12.75x104-370	2	32 C PS				Shutdown		39 8/30		10/15-10/22 Wks
W24x9x56-103	2	33 C PS				Shutdown		39 O		10/15-10/22 Wks
W24x7x55-62	1					Shutdown	38 8/29			11/12-11/19 Wks
W21x12.25x101-275	2	33 C PS				Shutdown				10/15-10/22 Wks
W21x8.25x48-93	1					Shutdown	39 8/29			11/19-11/26 Wks
W21x6.5x44-57	1					Shutdown	39 8/29	39 8/29		11/19-11/26 Wks
W18x11x76-311	2	33 C PS				Shutdown		39 O		10/22-10/29 Wks
W18x7.5x41-71	1					Shutdown			40 O	11/26-12/3 Wks
W18x6x35-46	1					Shutdown			40 O	11/26-12/3 Wks
W16x10.25x67-100	1					Shutdown				10/8-10/15 Wks
W16x7x36-57	1					Shutdown				10/8-10/15 Wks
W16x5.5x26-31	1			36 8/21		Shutdown				11/5-11/12 Wks
W14x16x455-730	2	34 C	34 C			Shutdown			40 O	11/5-11/12 Wks
W14x16x145-426	2		34 C PS	34 C PS		Shutdown			40 O	11/5-11/12 Wks
W14x14.5x90-132	2			35 8/17		Shutdown				10/8-10/15 Wks
W14x10x61-82	1					Shutdown		40 9/7	<<<<	11/19-11/26 Wks
W14x8x43-53	1					Shutdown		40 O	<<<<	11/19-11/26 Wks
W14x6.75x30-38	1					Shutdown				10/8-10/15 Wks
W14x5x22-26	1			36 8/21		Shutdown				11/5-11/12 Wks
W12x12x65-336	2			35 8/17		Shutdown			40 O	11/5-11/12 Wks
W12x10x53-58	1					Shutdown				10/8-10/15 Wks
W12x8x40-50	1					Shutdown				10/8-10/15 Wks
W12x6.5x26-35	1	34 C PS	34 C PS			Shutdown				10/22-10/29 Wks
W12x4x16-22	1	34 C PS				Shutdown				10/22-10/29 Wks
W10x10x49-112	1					Shutdown				10/15-10/22 Wks
W10x8x33-45	1	33 C PS				Shutdown				10/15-10/22 Wks
W10x5.75x22-30	1		34 C PS			Shutdown				10/29-11/5 Wks
W8x8x31-67	1		35 C PS			Shutdown				10/29-11/5 Wks
W8x6.5x24-28	1		35 C PS			Shutdown				10/29-11/5 Wks
W8x5.25x18-21	1	34 C PS				Shutdown				10/22-10/29 Wks
W6x6x15-25	1	34 C PS	<<<<			Shutdown				10/22-10/29 Wks
Week Beginning		13-Aug	20-Aug	27-Aug	3-Sep	10-Sep	17-Sep	24-Sep	1-Oct	
Standard Sections		33	34	35	36	37	38	39	40	
MC18x4x42.7-58	1					Shutdown				11/5-11/12 Wks
MC13x4x31.8x50	1					Shutdown				11/5-11/12 Wks
MC12x4x31-50	1					Shutdown				11/5-11/12 Wks
C15x3 3/8x33.9-50	1					Shutdown				10/29-11/5 Wks
C12x3x20.7-30	1					Shutdown				10/29-11/5 Wks
L8x8x1/2" - 1 1/8"	1		35 8/16			Shutdown				4th Qtr
L8x6x1/2" - 1"	1		35 8/16			Shutdown				4th Qtr
L8x4x1/2"-1"	1		35 8/16	35 8/16		Shutdown				4th Qtr
CZ13x41.2-51.2	1					Shutdown				TBA
S24x80-121	1					Shutdown	39 SA 8/29			TBA
S20x66-96	1					Shutdown		39 SA 8/29		TBA
S18x54.7-70	1					Shutdown				10/8-10/15 Wks SA
S15x42.9-50	1					Shutdown				TBA
S12x31.8-50	1					Shutdown				10/8-10/15 Wks
Week Beginning		13-Aug	20-Aug	27-Aug	3-Sep	10-Sep	17-Sep	24-Sep	1-Oct	
Piling Sections		33	34	35	36	37	38	39	40	
PS31	1					Shutdown				10/15-10/22 Wks
PS27	1					Shutdown				10/15-10/22 Wks
PZ40	1				36 C	Shutdown				11/12-11/19 Wks
PZ35	1				36 C	Shutdown				11/12-11/19 Wks
PZ27	1	33 C				Shutdown				10/15-10/22 Wks
PZ22	1	33 C				Shutdown				10/15-10/22 Wks
HP18	2					Shutdown			40 SA	11/5-11/12 Wks SA
HP16	2					Shutdown			40 SA	11/5-11/12 Wks SA
HP14x14.5x73-117	2		34 C			Shutdown			40 O	11/5-11/12 Wks
HP12x12x53-84	1					Shutdown	38 8/28			11/12-11/19 Wks
HP10x10x42-57	1	33 C				Shutdown				10/15-10/22 Wks
HP8x8x36	1		35 C	<<<<		Shutdown				10/29-11/5 Wks

I = Inquire O = Open PS = Planned Stock SA = Subject to Accumulation E = Controlled C = Closed