

Close Dates for all items, if available, are shown immediately behind the status of the book week.
 Status: C - Closed; E - Controlled; I - Inquire; O - Open; PS - Planned Stock; SA - Subject to Accum
 All sections close at 4 PM CST on the date indicated. Inquire items can close at any time.

Week Beginning		26-Mar	2-Apr	9-Apr	16-Apr	23-Apr	30-Apr	7-May	14-May	Projected Next Week
NYS Fiscal Week	Mill #	13	14	15	16	17	18	19	20	
W44x16x230-335	2		14 C	shutdown						5/28-6/4 Wks
W40x16x199-655	2		14 C	shutdown			18 O			5/28-6/4 Wks
W40x11.75x149-392	2		14 C	shutdown			18 O			5/28-6/4 Wks
W36x17x487-652	2		16 C	shutdown			18 O	18 O		5/28-6/4 Wks
W36x16 1/2x231-441	2		16 C	shutdown			18 O	18 O		5/28-6/4 Wks
W36x12x135-256	2		16 C	shutdown			>>>>	18 O		5/28-6/4 Wks
W33x15 3/4x201-387	2		16 C	shutdown				19 O		6/4-6/11 Wks
W33x11 1/2x118-169	2		16 C	shutdown				19 O		6/4-6/11 Wks
W30x15x173-433	2		16 C	shutdown	<<<<			19 O		6/4-6/11 Wks
W30x10 1/2x90-148	2		16 I 3/30	shutdown	<<<<			19 O		6/4-6/11 Wks
W27x14x146-368	2			shutdown	16 I 3/29				20 O	6/11-6/18 Wks
W27x10x84-129	2			shutdown	16 I 3/29				20 O	6/11-6/18 Wks
W24x12 3/4x104-370	2			shutdown	16 I 4/3				20 O	6/11-6/18 Wks
W24x9x56-103	2			shutdown	16 I 4/3				20 O	6/11-6/18 Wks
W24x7x55-62	1		14 C	shutdown	14 C			>>>>	19 O	6/11-6/18 Wks
W21x12 1/4x101-275	2			shutdown						5/14-5/21 Wks
W21x8 1/4x48-93	1			shutdown	14 C				20 O	6/18-6/25 Wks
W21x6 1/2x44-57	1			shutdown	14 C				20 O	6/18-6/25 Wks
W18x11x76-311	2	13 C		shutdown		>>>>	17 O			5/28-6/4 Wks
W18x7 1/2x41-71	1			shutdown	16 I 4/3					5/14-5/21 Wks
W18x6x35-46	1			shutdown	16 I 4/3					5/14-5/21 Wks
W16x10 1/4x67-100	1			shutdown	16 I 3/30	16 I 3/30				5/14-5/21 Wks
W16x7x36-57	1			shutdown		16 I 3/30				5/14-5/21 Wks
W16x5 1/2x26-31	1	13 C	13 C	shutdown			>>>>	18 O		6/4-6/11 Wks
W14x16x455-730	2			shutdown						5/21-5/28 Wks
W14x16x145-426	2			shutdown		17 O				5/21-5/28 Wks
W14x14 1/2x90-132	2	13 C		shutdown		17 O				5/28-6/4 Wks
W14x10x61-82	1			shutdown	16 I 3/27				20 O	6/18-6/25 Wks
W14x8x43-53	1			shutdown	16 I 4/3				20 O	6/18-6/25 Wks
W14x6 3/4x30-38	1			shutdown						5/14-5/21 Wks
W14x5x22-26	1	>>>>	13 C	shutdown			>>>>	>>>>	18 O	6/4-6/11 Wks
W12x12x65-336	2	14 C		shutdown			18 O			5/28-6/4 Wks
W12x10x53-58	1			shutdown		>>>>	17 I 3/30			5/21-5/28 Wks
W12x8x40-50	1			shutdown		>>>>	17 I 3/30			5/21-5/28 Wks
W12x6 1/2x26-35	1			shutdown			17 O			5/21-5/28 Wks
W12x4x16-22	1		14 C	shutdown						6/4-6/11 Wks
W10x10x49-112	1			shutdown		>>>>	17 I 3/29			5/21-5/28 Wks
W10x8x33-45	1			shutdown		>>>>	17 I 3/29			5/21-5/28 Wks
W10x5 3/4x22-30	1	12 C		shutdown			17 O			5/28-6/4 Wks
W8x8x31-67	1	12 C		shutdown			>>>>	17 O		5/28-6/4 Wks
W8x6 1/2x24-28	1	12 C		shutdown			>>>>	17 O		5/28-6/4 Wks
W8x5 1/4x18-21	1			shutdown		>>>>	17 O			6/25-7/2 Wks
W6x6x15-25	1			shutdown		>>>>	17 O			6/25-7/2 Wks
Stand Sections		26-Mar	2-Apr	9-Apr	16-Apr	23-Apr	30-Apr	7-May	14-May	
MC18x4x42.7-58	1	12 C		shutdown						5/28-6/4 Wks SA
MC13x4x31.8x50	1			shutdown						TBA
MC12x4x31-50	1	12 C		shutdown						5/28-6/4 Wks SA
C15x3 3/8x33.9-50	1			shutdown						5/21-5/28 Wks
C12x3x20.7-30	1			shutdown						5/21-5/28 Wks
L8x8x1/2" - 1 1/8"	1			shutdown			>>>>	18 O SA		TBA
L8x6x1/2" - 1"	1			shutdown			>>>>	18 O SA		TBA
L8x4x1/2"-1"	1			shutdown			>>>>	18 O SA		TBA
CZ13x41.2-51.2	1			shutdown						TBA
S24x80-121	1			shutdown						TBA
S20x66-96	1			shutdown	cancelled					TBA
S18x54.7-70	1			shutdown	16 I 4/3 SA					TBA
S15x42.9-50	1			shutdown			>>>>	18 O SA		TBA
S12x31.8-50	1			shutdown		>>>>	17 O SA			TBA
Piling Sections		26-Mar	2-Apr	9-Apr	16-Apr	23-Apr	30-Apr	7-May	14-May	
PS31	1		13 C	shutdown						5/28-6/4 Wks SA
PS27	1			shutdown						5/28-6/4 Wks SA
PZ40	1		13 C	shutdown						5/28-6/4 Wks SA
PZ35	1			shutdown						5/28-6/4 Wks SA
PZ27	1		14 C	shutdown						6/4-6/11 Wks SA
PZ22	1		14 C	shutdown						6/4-6/11 Wks SA
HP18	2			shutdown	16 O SA	16 O SA				6/11-6/18 Wks SA
HP16	2			shutdown		17 O SA				6/11-6/18 Wks SA
HP14x14.5x73-117	2	13 C		shutdown		17 O	17 O			5/28-6/4 Wks
HP12x12x53-84	2	14 C		shutdown			18 O			5/28-6/4 Wks
HP10x10x42-57	1			shutdown		17 I 3/29				5/21-5/28 Wks
HP8x8x36	1			shutdown		17 O				5/28-6/4 Wks