

Close Dates for all items, if available, are shown immediately behind the status of the book week.  
Status: C - Closed; E - Controlled; I - Inquire; O - Open; PS - Planned Stock; SA - Subject to Accumulation

All sections close at 4 PM CST on the date indicated. Inquire items can close at any time.

Week Beginning		28-Apr	5-May	12-May	19-May	26-May	2-Jun	9-Jun	16-Jun	Projected Next Week
NYS Fiscal Week	Mill #	18	19	20	21	22	23	24	25	
<b>Wide Flange</b>	<b>Mill #</b>									
W44x16x230-408	2	17 C				21 I 5/9				6/23-6/30 Wks
W40x16x199-655	2	17 C	17 C			22 I 5/9	22 I 5/9			6/23-6/30 Wks
W40x11.75x149-392	2	>>>>	17 C			>>>>	22 I 5/9			6/23-6/30 Wks
W36x17x487-652	2	>>>>	17 C			>>>>	22 I 5/10			6/23-6/30 Wks
W36x16 1/2x231-441	2		17 C				22 I 5/10			6/23-6/30 Wks
W36x12x135-387	2		17 C PS				22 I 5/10			6/23-6/30 Wks
W33x15 3/4x201-387	2		18 C				23 I 5/10			6/30-7/7 Wks
W33x11 1/2x118-169	2		18 C PS	18 C PS			23 I 5/10			6/30-7/7 Wks
W30x15x173-433	2		>>>>	18 C			23 I 5/13	23 I 5/13		6/30-7/7 Wks
W30x10 1/2x90-148	2			18 C PS			>>>>	23 O		6/30-7/7 Wks
W27x14x146-539	2			19 C				24 I 5/13		7/7-7/14 Wks
W27x10x84-129	2			19 C PS				24 O		7/7-7/14 Wks
W24x12 3/4x104-370	2			19 C PS				24 O		7/7-7/14 Wks
W24x9x56-103	2			19 C PS	19 C PS			24 O		7/7-7/14 Wks
W24x7x55-62	1	18 C PS				21 I 5/6				6/23-6/30 Wks
W21x12 1/4x101-275	2							24 O		7/7-7/14 Wks
W21x8 1/4x48-93	1	18 C PS				22 I 5/7				6/23-6/30 Wks
W21x6 1/2x44-57	1	18 C PS	18 C PS			22 I 5/7				6/23-6/30 Wks
W18x11x76-311	2	16 C PS				21 I 5/6				6/9-6/16 Wks
W18x7 1/2x41-71	1		20 C PS			22 O	22 O			6/30-7/7 Wks
W18x6x35-46	1		20 C PS				22 O			6/30-7/7 Wks
W16x10 1/4x67-100	1		>>>>	20 C			23 O			6/30-7/7 Wks
W16x7x36-57	1		>>>>	20 C PS			23 O			6/30-7/7 Wks
W16x5 1/2x26-31	1				21 I 5/1					6/16-6/23 Wks
W14x16x455-808	2				20 I 4/30				25 O	7/14-7/21 Wks
W14x16x145-426	2				20 C				25 O	7/14-7/21 Wks
W14x14 1/2x90-132	2				21 I 5/6	21 I 5/6				6/9-6/16 Wks
W14x10x61-82	1	>>>>	20 C			22 I 5/8				6/23-6/30 Wks
W14x8x43-53	1	>>>>	20 C PS			22 O				6/23-6/30 Wks
W14x6 3/4x30-38	1		>>>>	20 C PS			23 O			6/30-7/7 Wks
W14x5x22-26	1				21 I 5/1					6/16-6/23 Wks
W12x12x65-336	2	17 C PS		20 C		21 I 5/7				6/16-6/23 Wks
W12x10x53-58	1		>>>>	20 C PS			>>>>	23 O		6/30-7/7 Wks
W12x8x40-50	1		>>>>	20 C PS			>>>>	23 O		6/30-7/7 Wks
W12x6 1/2x26-35	1			20 I 4/29					25 O	7/14-7/21 Wks
W12x4x16-22	1									7/7-7/14 Wks
W10x10x49-112	1			20 C PS				24 O		7/7-7/14 Wks
W10x8x33-45	1			20 C PS				24 O		7/7-7/14 Wks
W10x5 3/4x22-30	1			21 I 4/29					25 O	7/14-7/21 Wks
W8x8x31-67	1			21 I 4/30					25 O	7/14-7/21 Wks
W8x6 1/2x24-28	1			>>>>	21 I 4/30				25 O	7/14-7/21 Wks
W8x5 1/4x18-21	1			20 C PS				24 O		7/7-7/14 Wks
W6x6x15-25	1			20 C PS				24 O		7/7-7/14 Wks
<b>Stand Sections</b>		<b>28-Apr</b>	<b>5-May</b>	<b>12-May</b>	<b>19-May</b>	<b>26-May</b>	<b>2-Jun</b>	<b>9-Jun</b>	<b>16-Jun</b>	
MC18x4x42.7-58	1									6/16-6/23 Wks
MC13x4x31.8x50	1									TBA
MC12x4x31-50	1									6/16-6/23 Wks
C15x3 3/8x33.9-50	1							24 O		8/4-8/11 Wks
C12x3x20.7-30	1							24 O		8/4-8/11 Wks
L8x8x1/2" - 1 1/8"	1				21 I 4/30					7/14-7/21 Wks
L8x6x1/2" - 1"	1				21 I 4/30					7/14-7/21 Wks
L8x4x1/2"-1"	1				21 I 4/30					7/14-7/21 Wks
CZ13x41.2-51.2	1	16 C								TBA
S24x80-121	1									6/23-6/30 Wks
S20x66-96	1									6/23-6/30 Wks
S18x54.7-70	1						>>>>	23 O		TBA
S15x42.9-50	1				21 I 5/1					TBA
S12x31.8-50	1			20 I 4/29						TBA
<b>Piling Sections</b>		<b>28-Apr</b>	<b>5-May</b>	<b>12-May</b>						
PS31	1									7/7-7/14 Wks
PS27	1									7/7-7/14 Wks
PZ40	1	18 C								7/7-7/14 Wks
PZ35	1	18 C								7/7-7/14 Wks
PZ27	1	16 C								7/7-7/14 Wks
PZ22	1	16 C								7/7-7/14 Wks
HP18	2			>>>>	20 C					TBA
HP16	2				20 C					TBA
HP14x14.5x73-117	2				>>>>	21 I 5/2				6/9-6/16 Wks
HP12x12x53-84	2	17 C				21 I 5/2				6/16-6/23 Wks
HP10x10x42-57	1			20 C				24 O		7/7-7/14 Wks
HP8x8x36	1			21 I 4/30					25 O	7/14-7/21 Wks

