

Nucor-Yamato Proposed Roll/Close Schedule * ISO 9001:2015 Registered * September 23, 2020
 Close Dates for all items, if available, are shown immediately behind the status of the book week
 Highlighted items will close in the next week - All sections close at 4 PM Central on the date indicated

Week Beginning		20-Sep	27-Sep	4-Oct	11-Oct	18-Oct	25-Oct	1-Nov	8-Nov	
NYS Fiscal Week		38	39	40	41	42	43	44	45	
Wide Flange Sections	Mill #									Projected next roll week
W44x16x230-335	2			Shutdown	Shutdown			45 O	<<<<	1/3-1/10 Wks
W40x16x199-593	2			Shutdown	Shutdown			45 O	<<<<	1/3-1/10 Wks
W40x11.75x149-392	2			Shutdown	Shutdown	42 C		45 O	45 O	11/29-12/6 Wks
W36x17x487-652	2			Shutdown	Shutdown				45 O	1/3-1/10 Wks
W36x16 1/2x231-441	2			Shutdown	Shutdown				45 O	1/3-1/10 Wks
W36x12x135-256	2			Shutdown	Shutdown	42 C			45 O	12.6-12/13 Wks
W33x15 3/4x201-387	2			Shutdown	Shutdown					11/15-11/22 Wks
W33x11 1/2x118-169	2			Shutdown	Shutdown	42 C				11/15-11/22 Wks
W30x15x173-391	2			Shutdown	Shutdown					11/15-11/22 Wks
W30x10 1/2x90-148	2			Shutdown	Shutdown	42 I 9/28				11/15-11/22 Wks
W27x14x146-368	2	37 C		Shutdown	Shutdown		42 I 9/28			11/15-11/22 Wks
W27x10x84-129	2	37 C PS		Shutdown	Shutdown		42 I 9/29			11/15-11/22 Wks
W24x12 3/4x104-370	2	37 C		Shutdown	Shutdown		42 I 9/29			11/15-11/22 Wks
W24x9x56-103	1/2	38 C PS		Shutdown	Shutdown	43 I 9/28				11/22-11/29 Wks
W24x7x55-62	1			Shutdown		42 I 9/28				11/15-11/22 Wks
W21x12 1/4x101-275	2	38 C		Shutdown	Shutdown					11/22-11/29 Wks
W21x8 1/4x48-93	1			Shutdown			43 I 10/7			11/15-11/22 Wks
W21x6 1/2x44-57	1			Shutdown			43 I 10/8			11/15-11/22 Wks
W18x11x76-311	2		39 C PS	Shutdown	Shutdown			44 O		11/29-12/6 Wks
W18x7 1/2x41-71	1			Shutdown				44 O		11/15-11/22 Wks
W18x6x35-46	1			Shutdown				44 O		11/15-11/22 Wks
W16x10 1/4x67-100	1			Shutdown				44 O		11/22-11/29 Wks
W16x7x36-57	1			Shutdown				44 O		11/22-11/29 Wks
W16x5 1/2x26-31	1		42 I 9/23	Shutdown	42 I 9/23				45 O	12/13-12/20 Wks
W14x16x455-730	2	39 C		Shutdown	Shutdown					11/22-11/29 Wks
W14x16x145-426	2	38 C	38 C	Shutdown	Shutdown			43 I 10/8		11/22-11/29 Wks
W14x14 1/2x90-132	1			Shutdown	42 I 9/24					11/29-12/6 Wks
W14x10x61-82	1			Shutdown			44 I 10/8			11/15-11/22 Wks
W14x8x43-53	1			Shutdown			44 O	44 O		11/15-11/22 Wks
W14x6 3/4x30-38	1	37 C PS		Shutdown				45 O		11/29-12/6 Wks
W14x5x22-26	1			Shutdown	42 I 9/23					11/8-11/15 Wks
W12x12x65-336	2		39 C PS	Shutdown	Shutdown			44 O		11/29-12/6 Wks
W12x10x53-58	1	38 C PS		Shutdown				45 O		11/29-12/6 Wks
W12x8x40-50	1	38 C PS		Shutdown				45 O		11/29-12/6 Wks
W12x6 1/2x26-35	1	38 C PS	38 C PS	Shutdown					45 O	11/29-12/6 Wks
W12x4x16-22	1		41 C PS	Shutdown						11/29-12/6 Wks
W10x10x49-112	1	38 C PS		Shutdown				45 O		11/29-12/6 Wks
W10x8x33-45	1	38 C PS		Shutdown				45 O		11/29-12/6 Wks
W10x5 3/4x22-30	1		39 C PS	Shutdown					45 O	12/6-12/13 Wks
W8x8x31-67	1		41 C PS	Shutdown					45 O	12/6-12/13 Wks
W8x6 1/2x24-28	1		41 C PS	Shutdown					45 O	12/6-12/13 Wks
W8x5 1/4x18-21	1	38 C PS		Shutdown						11/29-12/6 Wks
W6x6x15-25	1	38 C PS		Shutdown						11/29-12/6 Wks
Standard Sections		20-Sep	27-Sep	4-Oct	11-Oct	18-Oct	25-Oct	1-Nov	8-Nov	
MC18x4x42.7-58	1			Shutdown	42 C PS					TBA
MC13x4x31.8x50	1			Shutdown						TBA
MC12x4x31-50	1		39 C PS	Shutdown						TBA
C15x3 3/8x33.9-50	1		39 C PS	Shutdown						TBA
C12x3x20.7-30	1	38 C PS		Shutdown						TBA
L8x8x1/2" - 1 1/8"	1		42 C PS	Shutdown	<<<<					TBA
L8x6x1/2" - 1"	1		42 C PS	Shutdown	<<<<					TBA
L8x4x1/2" - 1"	1		42 C PS	Shutdown	<<<<					TBA
CZ13x41.2-51.2	1			Shutdown						TBA
S24x80-121	1			Shutdown						TBA
S20x66-96	1			Shutdown						TBA
S18x54.7-70	1			Shutdown						TBA
S15x42.9-50	1			Shutdown						TBA
S12x31.8-50	1	38 C PS		Shutdown						TBA
Piling Sections		20-Sep	27-Sep	4-Oct	11-Oct	18-Oct	25-Oct	1-Nov	8-Nov	
PS31	1	38 C		Shutdown						11/29-12/6 SA Wks
PS27	1	38 C		Shutdown						11/29-12/6 SA Wks
PZ40	1		42 C	Shutdown	<<<<					12/6-12/13 SA Wks
PZ35	1			Shutdown						12/6-12/13 SA Wks
PZ27	1		41 C	Shutdown						12/6-12/13 SA Wks
PZ22	1		41 C	Shutdown						12/6-12/13 SA Wks
HP18	2		38 C	Shutdown						11/22-11/29 SA Wks
HP16	2		39 C	Shutdown						11/29-12/3 SA Wks
HP14x14.5x73-117	1			Shutdown	42 I 9/24	42 I 9/24			45 O	12/13-12/20 Wks
HP12x12x53-84	1			Shutdown			43 I 10/7			11/15-11/22 Wks
HP10x10x42-57	1	38 C		Shutdown				45 O	<<<<	11/29-12/6 Wks
HP8x8x36	1		41 C	Shutdown					45 O	12/6-12/13 Wks

I = Inquire O = Open PS = Planned Stock SA = Subject to Accumulation E = Controlled C = Closed