

Close Dates for all items, if available, are shown immediately behind the status of the book week.

Status: C - Closed; E - Controlled; I - Inquire; O - Open; PS - Planned Stock; SA - Subject to Accumulation

All sections close at 4 PM CST on the date indicated. Inquire items can close at any time.

Week Beginning		28-Sep	5-Oct	12-Oct	19-Oct	26-Oct	2-Nov	9-Nov	16-Nov	23-Nov	30-Nov	
NYS Fiscal Week		39	40	41	42	43	44	45	46	47	48	Projected Next Week
Wide Flange	Mill #											
W44x16x230-408	2										48 I	2/1-2/8 Wks
W40x16x199-655	2	38 C									48 C	2/1-2/8 Wks
W40x11.75x149-392	2	38 C									48 C	2/1-2/8 Wks
W36x17x487-652	2	39 C										11/30-12/7 Wks
W36x16 1/2x231-441	2	39 C	39 C									11/30-12/7 Wks
W36x12x135-387	2		39 C									11/30-12/7 Wks
W33x15 3/4x201-387	2		40 C	40 C								11/30-12/7 Wks
W33x11 1/2x118-169	2		>>>>	40 C								11/30-12/7 Wks
W30x15x173-433	2			40 C								11/30-12/7 Wks
W30x10 1/2x90-148	2			40 C	40 C							12/14-12/21 Wks
W27x14x146-539	2			>>>>	41 C							12/14-12/21 Wks
W27x10x84-129	2				41 C							12/14-12/21 Wks
W24x12 3/4x104-370	2				41 C	41 C						12/14-12/21 Wks
W24x9x56-103	2					42 C						12/14-12/21 Wks
W24x7x55-62	1			shutdown								11/23-11/30 Wks
W21x12 1/4x101-275	2					42 C						12/14-12/21 Wks
W21x8 1/4x48-93	1			shutdown								11/30-12/7 Wks
W21x6 1/2x44-57	1			shutdown								11/30-12/7 Wks
W18x11x76-311	2									47 I 10/20		1/25-2/1 Wks
W18x7 1/2x41-71	1		38 C	shutdown								12/14-12/21 Wks
W18x6x35-46	1		38 C	shutdown								12/28-1/4 Wks
W16x10 1/4x67-100	1			shutdown		40 C						12/28-1/4 Wks
W16x7x36-57	1			shutdown		40 C						12/28-1/4 Wks
W16x5 1/2x26-31	1			shutdown					47 I 10/13	47 I 10/13		1/25-2/1 Wks
W14x16x455-873	2					42 I 10/2	42 I 10/2					12/28-1/4 Wks
W14x16x145-426	2						43 I 10/2	43 I 10/2				12/28-1/4 Wks
W14x14 1/2x90-132	2							43 I 10/16	43 I 10/16			12/28-1/4 Wks
W14x10x61-82	1	37 C		shutdown								12/7-12/14 Wks
W14x8x43-53	1	37 C		shutdown								12/7-12/14 Wks
W14x6 3/4x30-38	1			shutdown		40 C						1/4-1/11 Wks
W14x5x22-26	1			shutdown						47 I 10/13		2/1-2/8 Wks
W12x12x65-336	2									47 I 10/20	47 I 10/20	1/25-2/1 Wks
W12x10x53-58	1			shutdown			43 C					1/4-1/11 Wks
W12x8x40-50	1			shutdown			43 C					1/4-1/11 Wks
W12x6 1/2x26-35	1			shutdown				45 I 10/6				1/18-1/25 Wks
W12x4x16-22	1			shutdown							48 I 10/14	2/1-2/8 Wks
W10x10x49-112	1			shutdown			44 C	44 C				1/18-1/25 Wks
W10x8x33-45	1			shutdown			44 C					1/18-1/25 Wks
W10x5 3/4x22-30	1			shutdown				45 I 10/6				1/18-1/25 Wks
W8x8x31-67	1			shutdown				45 I 10/6	45 I 10/6			1/25-2/1 Wks
W8x6 1/2x24-28	1			shutdown					45 I 10/6			1/25-2/1 Wks
W8x5 1/4x18-21	1			shutdown								TBA
W6x6x15-25	1			shutdown								TBA
Stand Sections		28-Sep	5-Oct	12-Oct	19-Oct	26-Oct	2-Nov	9-Nov	16-Nov	23-Nov	30-Nov	
MC18x4x42.7-58	1			shutdown					46 I 10/15			TBA
MC13x4x31.8x50	1			shutdown					46 I SA 10/8			TBA
MC12x4x31-50	1			shutdown					46 I SA 10/8			TBA
C15x3 3/8x33.9-50	1			shutdown				45 I 10/8				TBA
C12x3x20.7-30	1			shutdown				45 I 10/8				TBA
L8x8x1/2" - 1 1/8"	1			shutdown								TBA
L8x6x1/2" - 1"	1			shutdown								TBA
L8x4x1/2"-1"	1			shutdown								TBA
CZ13x41.2-51.2	1			shutdown								TBA
S24x80-121	1			shutdown								11/30-12/7 Wks SA
S20x66-96	1			shutdown								11/30-12/7 Wks SA
S18x54.7-70	1			shutdown								12/28-1/4 Wks SA
S15x42.9-50	1			shutdown								TBA
S12x31.8-50	1			shutdown								TBA
Piling Sections		28-Sep	5-Oct	12-Oct	19-Oct	26-Oct	2-Nov	9-Nov	16-Nov	23-Nov	30-Nov	
PS	1			shutdown						47 I SA 10/13		TBA
PZ40	1			shutdown								11/30-12/7 Wks SA
PZ35	1			shutdown								11/30-12/7 Wks SA
PZ27	1			shutdown							48 I SA 10/13	2/8-2/15 Wks SA
PZ22	1			shutdown							48 I SA 10/13	2/8-2/15 Wks SA
HP18	2					42 I 10/6						12/21-12/28 Wks SA
HP16	2											12/21-12/28 Wks SA
HP14x14.5x73-117	2								46 I 10/16	46 I 10/16		1/25-2/1 Wks SA
HP12x12x53-84	1	38 C	38 C	shutdown								12/14-12/21 Wks SA
HP10x10x42-57	1			shutdown		>>>>	43 C					1/18-1/25 Wks SA
HP8x8x36	1			shutdown				45 I 10/6				1/25-2/1 Wks